RISO INC. TECHNICAL INFORMATION BULLETIN

Subject: Master Holder | Bulletin No: 35

☐ Factory Modification ☐ Field Modification ☐ Safety Information ☐ Technical Information ■ General Information ■ Adv. Tech Information	Applies to: 2500 2700 3500	Modification Schedule: ☐ TBS ■ Next Call ☐ Next PM ■ As Necessary	Factory Installed _____ Field Installed _____ Fitting Time 30 min.

Master Holder Part # 007-12121 (89¢ each)

1. Cut and remove central piece of the sheet: clamp plate.





Check that this corne does not hit the clam plate.

Put the holder mylar under the clamp plate.

Set the corner of tl Holder Mylar on the edge of the index; drum (orange sheet)

2. Fold the holder mylar as shown



3. Stick the master holde on the index drum (orange sheet).



Orange Index; Drum

Clamp Plate and holder. Metal Should be flush.



4.

Issue Date	Effective Date	Supersedes Bulletin	Date	Page No.
4/4/89	4/4/89		4/4/89	1 of : 1